

FIG. 1




FIG. 2




FIG. 3A

Standard




FIG. 3B

Double




FIG. 3C

Straight




FIG. 4A

Standard




FIG. 4B

Double





FIG. 4C

Straight



■ 0A
 ● 40A
 ▲ 70A

FIG. 5A

Standard




FIG. 5B

Double





FIG. 5C

Straight



■ 40A
 ● 70A

FIG. 6A





FIG. 6B



MAIN EFFECTS PLOT (DATA MEANS) FOR POWER




Fig. 7a

MAIN EFFECTS PLOT (DATA MEANS) FOR PRESSURE RAT




Fig. 7b